


LumiNode Radiation Shield – Quick Guide

WARNING! READ BELOW CAREFULLY BEFORE USE
THE NUT SHOULD BE SECURED VERY CAREFULLY TO AVOID CROSS-THREADING!

INSTRUCTIONS

1. Using the provided nuts, attach the Radiation Shield bracket to the back of the LumiNode on top of the pre-installed nuts (circled below). Do **NOT** remove the pre-installed nuts.
2. Line up the holes in the Radiation Shield with one of the two sets of holes on the bracket. The set of holes you use will determine the angle of the Radiation Shield (see below).
3. Secure the Radiation Shield in place with the provided screws. Once again, do not overtighten.



The 1st set of holes on the flat section of the bracket gives the Radiation Shield a slight angle. The 2nd set of holes allows the Radiation Shield to be installed parallel to the Node.

Position 1

Position 2

